FORM MR-AR (Revised 3/98) RECEIVED

JAN 30 2001

DIVISION OF OIL, GAS AND MINING



STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1	Gene	ral Information			
	I.	Report Time Period: From (mo./yr.) 1/1/00 To (mo./yr.) 12/31/00			
	2.	DOGM File Number (Mine S / 027/ 089			
	3.	Mine Name: Utah State Lease			
	4.	Mineral(s) Mined (or permitted to mine): Perlite			
	5.	Type of mine ☐ Surface Mine or ☐ Underground Mine			
	6.	Legal Description (Location of Lands Affected):			
		1/4,1/4, NW 1/4, Section 2 , Township 24S , Range 9W			
		1/4, 1/4, 1/4, Section, Township Range			
		1/4, 1/4, 1/4, Section, Township Range			
7.	Name of Operator or Company: World Minerals, Inc.				
	8.	Permanent Street Address: PO Box 287			
		City, State, Zip: La Grande, Oregon 97850			
		Phone: 541/963-3987 Fax: 541/963-3995			
	9. Company Representative (or designated operator):				
		Name: Joseph Lévay			
		Title: Chief Geologist			
	Business Address: PO Box 287				
		City, State, Zip: La Grande, OR 97850			
		Phone: <u>541/963-3987</u> Fax: <u>541/963-3995</u>			
		Please check if any of the above information has changed since previous year.			
Н.	Mining and Reclamation				
	I.	Was there any mine related activity during the past year? Yes □ No □			
	2.	If no - what was the last year of activity?			
	3.	If yes - how much ore or mineral was mined? About 50 Tons			

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year. 50 tons of crude Perlite was trucked by contractor. Perlite ore was crushed, loaded into		
		to Barcelona, Spain for mill and expansion testing. No new	
	surface disturbances occurred during	g the past year.	
5.	How much additional acreage w	vas disturbed during the past year? None	
6.	How much acreage was reclaimed during the past year? None		
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed and an evaluation of the results		
	Reclamation work was not complet	ed during the year 2000.	
8.	What is the <u>total</u> disturbed acres	age of entire project at years end? 0.471 Acres	
9.	d/or reclamation plans for the upcoming year. on and diamond drilling.		
NOTE:	Section Ill., "Additional Informat	ion" applies only to large mining operations.	
III. <u>Additional</u>	<u>Information</u>		
I	An updated surface facilities map should be attached if there have been significant chang the previous map was submitted.		
2.	ts that are required under the terms of the approved notice of		
IV. <u>Signature</u>	Requirement		
I her	eby certify that the foregoing is	true and correct.	
	Name (Typed or Print):	Joseph Lévay	
	Title of Operator:	Chief Geologist	
	Signature of Operator:	Joseph Livan	
	Date:	January 29, 2001	
ib aAfortns\MR-AR		7	